

Section 1

Reporting Month Statistics – Quick Overview

Reporting Month	Month Fatalities	Month Critical Injuries	Month Total
May 2017	1	18	19

Provincial Coordinator's Comments

With the recent discussions around CSA standard Z259.2.5-12 for fall arresters and vertical lifelines I have had the opportunity to meet with multiple stakeholders to discuss their concerns on the standard.

Beyond some of the more complicated application concerns I have heard numerous misconceptions around when travel restraint is appropriate versus fall arrest. The inaccurate applications that have come to my attention leave me feeling very uncomfortable that some workers are under the impression that they are adequately protected when in fact that have built a false sense of security when selecting travel restraint in situations where it simply cannot apply.

As a health and safety system we all need to evaluate our workers knowledge level of fall protection systems and scenarios to ensure that workers have a very clear understanding of how the various methods of fall protection apply to the specific work they are performing. We must also ensure that they clearly understand the limitations each system presents. I would like to remind all employers, supervisors and workers that there are two sections in regulation that deal with fall protection training, the first is the standard around Working at Heights under section 7(1) of O.Reg 297/13 and the second is under section 26.2(1) under O. Reg 213/91 to address sector and site specific applications. Both of these sections are mandatory when a worker is working at heights in construction.

Although the standard on Working at Heights is a step in the right direction, it is generic to all fall protection scenarios in construction. Employers have the duty to ensure that the fall protection system selected is appropriate to protect the worker for the particular job or scenario that the worker is exposed to. The employer also has the duty to ensure that the workers understand the differences between the methods of fall protection and how to apply them to provide the greatest level of protection in-line with the hierarchy of fall protection.

In addition, employers need to consider their fall protection choice carefully. We often encounter workplace parties who have selected a very basic fall protection system without considering the needs of the worker or the task at hand or additional hazards that may create additional hazards to certain types of equipment. Not only can this leave the worker exposed to risk, but can also make the use of system cumbersome which may frustrate the worker and ultimately discourage the use of the system. It should go without saying that an unconnected system provides no protection at all, and yet we see it regularly.

It is important to remember that there are various systems available for the potential set ups that workers may encounter on the job site. You may need consider a system that goes beyond the commonly used rope grab and lifeline. Research the various pieces of fall protection equipment to find the best system(s) for the work you do.

Please take the time to ensure your workers fully understand and appreciate the various fall protection set ups as well as the type of equipment required to effectively perform the task.

Falls continue to be the #1 traumatic fatality in construction. We need to continuously improve how we educate and promote the consistent and appropriate use of fall protection systems in our industry.

Brian Barron

Provincial Coordinator
Construction Health and Safety Program
Ontario Ministry of Labour

Section 2

MOL Current Events

- **2017-2018 Blitz and Initiatives Schedule**
https://www.ontario.ca/page/workplace-inspection-blitzes-and-initiatives?_ga=1.136254456.895245737.1480564355
- **Extended Working at Heights transition period by 6 months**
 The Ministry has now extended Working at Heights transition period by six (6) months to October 1, 2017 for workers enrolled in a CPO-approved working at heights training program prior to April 1 2017 and scheduled to complete the training before October 1, 2017.
<https://www.labour.gov.on.ca/english/hs/topics/heights.php>
- **Blitz Results: Electrical Blitz Hazards 2016**
https://www.labour.gov.on.ca/english/hs/sawo/blitzes/blitz_report84.php
- **Blitz Results: Mobile Cranes and Material Hoisting 2016**
https://www.labour.gov.on.ca/english/hs/sawo/blitzes/blitz_report80.php
- **Spotlight New Construction Amendments Come Into Effect January 1**
<https://www.labour.gov.on.ca/english/hs/topics/construction.php>
- **Electrical Hazard Fact Sheet (Nov 2016)**
https://www.labour.gov.on.ca/english/hs/sawo/pubs/fs_electrical.php
- **Workplace Violence and Harassment – Code of Practice (effective Sept 8, 2016)**
<https://www.labour.gov.on.ca/english/hs/pubs/harassment/index.php>
- **Safe At Work Ontario Annual Report - Results for April 2014 - March 2015 (20 April 2016)**
<http://www.labour.gov.on.ca/english/hs/sawo/report/index.php>
- **Working at Heights Training (content reviewed March 2016)**
http://www.labour.gov.on.ca/english/hs/topics/heights.php?utm_source=molwebsite&utm_medium=banner&utm_content=spotlights_EN&utm_campaign=WorkingAtHeights
- **Occupational Exposure Limits**
<http://www.labour.gov.on.ca/english/about/consultations/oels/index.php>
- **Replacing Your Roof (content reviewed March 2016)**
http://www.labour.gov.on.ca/english/resources/roofing.php?utm_source=molwebsite&utm_medium=banner&utm_content=spotlights_EN&utm_campaign=RoofingPilot
- **Alert: Elevating Work Platform Crushing Hazard (April 2016)**
<http://www.labour.gov.on.ca/english/hs/pubs/alerts/a36.php>

Section 3

Case 1

Director of Roofing Company Jailed, Fined \$10,000 for Failure to Follow Safety Rules

May 18, 2017 5:15 P.M.

Ministry of Labour

BELLEVILLE, ON - An employer with two previous convictions for safety violations has been sentenced to one day imprisonment and a fine of \$10,000 for ignoring safety regulations. No one fell or was injured.

The employer, Steve Bell, was charged with failing as an employer to ensure a worker was adequately protected from falling. By law the worker should have been using a travel restraint system, fall-restricting system, fall arrest system or a safety net.

On October 7, 2015, a Ministry of Labour inspector attended a residence in Belleville and observed a roofer working at a height of more than three metres (about 26 feet) without being protected by fall protection. The worker's employer, Steve Bell, was later charged with the offence.

Bell had two prior convictions for the same offence. One was a conviction in 2013 with a fine of \$2,000 and the other was a conviction in 2015 with a fine of \$4,500; no one fell or was injured. These convictions fall under the Construction Projects Regulation (Regulation 213/91) and the Occupational Health and Safety Act.

Justice of the Peace Christopher I. Peltzer passed sentence in Belleville court on May 18, 2017.

The court also imposed a 25-per-cent victim fine surcharge as required by the Provincial Offences Act. The surcharge is credited to a special provincial government fund to assist victims of crime.

Court Information at a Glance

Location:

Provincial Offences Court/Ontario Court of Justice

235 Pinnacle Street

Belleville, Ontario

Judge:

Justice of the Peace Christopher I. Peltzer

Date of Sentencing:

May 18, 2017

Defendant:

Steve Bell

Belleville, Ontario

Matter:

Occupational health and safety

Conviction:

Occupational Health and Safety Act

Section 25(1)(c)

Regulation 213/91 (Construction Projects Regulation)

Section 26.1(2)

Section 4

Fatality & Critical Injury Year-to-Date Overview - Construction Sector

	2017 1st January – May 31	2016 1st January –May 31 comparison with last year
Fatalities	7	4
Critical Injuries	88	40

** NOTE: These figures represent preliminary data, and are not to be considered official statistics from the Ministry of Labour. Official statistics will be issued quarterly by the Program Analysis, Evaluation and Outcomes Unit of the Occupational Health and Safety Branch of the Ministry of Labour.*

REPORTING MONTHS: 1st – 31st May 2017, Monthly Summary Report

May 2017 Fatalities (1)

NOTE: Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry’s data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what actually occurred at the workplace.

By Sector	<ul style="list-style-type: none"> 1 - NECC , Not elsewhere captured construction
Brief Summary NOTE: These entries are in ascending date order (i.e. 1st to 31st) not sector order. See Section 5 for additional entry details.	<ul style="list-style-type: none"> 16-May-17 Western Region A worker fell approx. 25 feet while working on the roof trusses of a barn. The worker did not regain consciousness

May 2017 Critical Injuries (18)

NOTE: Data are subject to change due to updates in the enforcement database. Only events reported to the ministry are included here. Except for fatalities, event categories in the ministry’s data set are based on what was assigned at the time of the initial report to the ministry. The reported event category may not represent what actually occurred at the workplace.

<p>By Sector</p>	<ul style="list-style-type: none"> • 1-ROAD Highway & Road Construction • 4-RESS Single Family Housing • 1-INST Institutional Building Construction • 3-COMM Commercial Building Construction (one incident had 2 workers) • 1-RESM Apartment & Other Multiple Housing • 1-SUBW Subway • 2-PAVE Asphalt Paving • 2-NECC Not elsewhere captured construction • 1-CONY Construction premises • 1-SEWW Sewer/Watermain Construction
<p>Brief Summary</p>	<ul style="list-style-type: none"> • Worker fractured ankle when he slipped on a muddy bank and fell approx. two feet to the ground below. • Worker fell off ladder against side of house, approx. ten-twelve feet and fracture forearm and wrist. • Worker was struck by backhoe sustaining internal injuries and broken pelvis. • Worker fell out of telehandler and sustained fractured ribs and hip. • Frammer fell off the roof while installing sheathing resulting in fracture to leg. • Worker slipped on a small ramp and fractured wrist. • Worker fell five feet off scaffold platform and fractured their arm. • Worker fell 8 to 10 ft when the ladder slipped down and the worker fell onto a concrete rear patio. The worker broke left rib had and difficulty breathing. • Construction fence fell onto worker who sustained a fractured arm. • A truck driver broke their arm when disconnecting the trailer from the truck; the 'tongue' of the trailer pinned the worker's arm between it and the tow point. • A worker walking alongside an asphalt paver stepped on a patch of clay which broke, causing the worker to roll and fracture their ankle. • Worker was moving material with a jack when the material fell off the jack and landed on their foot and fracturing their foot. • Two workers on elevating work platform were injured when the boom failed and fell to the ground. Workers may have lost consciousness. MOL confirmed critical injuries sustained by both workers. • Worker fell from a ladder and grabbed the ladder on the way down cutting their hand while falling to the ground at a height of 6 or 7 ft high. The worker fractured their wrist.

- | | |
|--|---|
| | <ul style="list-style-type: none">• Worker fell from a ladder to concrete walkway and sustained head injuries• Worker was working as a signalman and was struck by a vehicle sustaining critical injuries.• Worker was installing corner bead off of a two-step bench when bench collapsed and fractured workers wrist and elbow. |
|--|---|

Section 5**Fatality & Critical Injury Year-to-Date Summaries*- Construction Sector**

*All new entries (current month and reconciled data) appear in **bold**.

NOTE: Some detail will inevitably be missing from the PLMHSC Report. The document is intended to provide an initial overview, not a comprehensive report. Annual data reporting approved by the Director should be used by stakeholders if they wish to see all data available to the Ministry related to an event.

Fatalities Year-to-Date Summary:**Total Year-to-Date Fatalities:**

Note 1: Ages will be included when available.

Note 2: Reconciled data appears in bold
Central West

#	Date of Incident	Region	Sector	Occupation	Details (as reported to MOL)
1	January 16 2017	Central East	RESM Condominium project	Worker	Worker was cleaning a concrete mixing machine and was pulled inside, resulting in fatal injuries.
2	2017-Mar-08	Western	RESM	Worker	A masonry block wall collapsed on a worker on the 3rd floor of townhouse project
3	2017-Mar-27	Central East	RESM	Worker	Worker was unloading a concrete pre-cast panel from a truck when it fell on the worker.
4	2017-Mar-3	Eastern	RESS	Worker	Worker fell off the roof approximately 9 feet to deck and approximately another 9 feet to the ground. April 22 2017 Worker succumbed to injuries
5	2017-April-6	Northern	MINP (Project at a Mine)	Worker	Dump truck operator was pinned underneath a set of dual tires on his tri-axel dump truck
6	2017-April-10	Northern	NECC	Worker	The worker fell from a suspended ceiling.
7	2017-May-16	Western	NECC	Worker	A worker fell approx. 25 feet while working on the roof trusses of a barn. The worker did not regain consciousness

Critical Injuries Year-to-Date Summary (January 1st to January 27th 2017): Total Year-to-Date Critical Injuries:

Note 1: Ages will be included when available.

Note 2: Reconciled data appears in bold

#	Date of	Region	Sector	Occurrn	Details (as reported to MOL)
1	04-Jan-17	Western	RESS	Worker	A worker cutting weather stripping off door with utility knife, cut himself in the arm and lost consciousness.
2	09-Jan-17	Central east	RESM	Worker	A worker was critically injured due to collapsed trench. The worker was fixing a leak in a pipe when the trench collapsed and a rock/frozen earth fell on the worker.
3	10-Jan-17	Central west	RESM	Worker	A worker sustained four fractures when operator of mini excavator ran over worker's foot.
4	10-Jan-2017	Eastern	RESS	Worker	A worker slipped and fell 25 ft off upper roof of a single family home build resulting in a loss of consciousness, fractured back and leg.
5	16-Jan-17	Central East	RESM	Worker	A worker assisting a crane operator in lifting a load of plywood got his hands caught between the chains holding the load up and the load, which severed the index and middle fingers on his left hand.
6	19-Jan-17	Northern	COMM	Worker	Two workers were cutting concrete and one worker lost consciousness due to confirmed exposure to carbon monoxide.
7	25-Jan-17	Central west	RESS	Worker	Worker fell off step ladder and fractured wrist.
8	24-01-2017	Central West	RESS	Worker	Worker fell from 2nd level of scaffolding & sustained head injuries
9	25-01-2017	Central west	INDU	Worker	Worker lost consciousness falling backwards and hitting head on concrete. The worker was moving a mechanical unit into the building holding a strap and the strap broke. When the strap broke, the worker took several steps backwards, their hard hat fell off their head and the worker fell hitting their head on the concrete.
10	26-01-2017	Western	RESM	Worker	Drywaller fell from scaffolding - 10-12 feet and broke ankle.
11	27-01-2017	Central west	RESS	Worker	Worker hit by a truck on construction site and sustained multiple injuries.
13	04-02-2017	Central west	RESS	Worker	Worker lost balance on top step hit chest against 2x4 and sustained 3 fractures ribs, punctured lung and fractured wrist.
14	06-02-2017	Western	RESM	Worker	Worker on scaffold approximately 3-4 ft high removing tarps when worker fell onto concrete pad in parking garage. Worker sustained head injury and fractures to both wrists.
15	06-02-2017	Western	INST	Worker	Worker was alone on a construction site performing electrical work on an out building in a park. Worker fell off top of the ladder (10 fee)Worker suffered fracture to arm

MOL REPORT TO PLMHSC –JUNE 2017 MEETING

16	08-02-2017	Central West	RESS	Worker	Worker slipped on ice and fell and lost consciousness at new construction residential site.
17	14-02-2017	Western	INST	Worker	Worker was setting up a concrete form and fell off the ladder and landed on his wrist. Worker suffered a fractured wrist, rib and cut to head.
18	15-02-2017	Central West	COMM	Worker	Worker doing roof renovations fell through to floor about 20 feet and sustained multiple injuries.
19	15-02-2017	Western	INDU	Worker	Worker performing electrical work on the ceiling roof level when he fell approximately 40ft and lost consciousness and significant amount of blood, suffered head trauma and injured left wrist. He was wearing a harness but was not clipped in.
20	16-02-2017	Central West	RESM	Worker	Worker walking backwards while unloading steel from a truck using a crane, missed a step and fell down resulting in fractured ankle.
21	20-02-2017	Western	INDU	Worker	Worker was using pry bar on platform that was 2 feet up when the bar slipped while exerting pressure causing the worker to fall and break arm.
22	21-02-2017	Central East	RESM	Worker	Worker was cutting concrete with a saw - CO levels emitted from machine resulted in loss of consciousness.
23	22-02-2017	Central West	EXC	Worker	Worker was exiting a trench via a ladder, he fell backwards off the ladder and into the trench, fell approximately 7-10 ft and lost consciousness.
24	24-02-2017	Central East	RESM	Worker	Worker received injury to chest with nail gun
25	27-02-2017	Central West	RESM	Worker	Worker stepped on a piece of debris, sustained hairline fracture to left ankle
26	01-03-2017	Eastern	RAIL	Worker	Worker caught foot on a protruding re-bar and fell forward resulting in unconsciousness, herniated disc and face lacerations.
27	01-03-2017	Central east	COMM	Worker	Worker was installing glass panel which fell on worker resulting in fractured right leg.
28	02-03-2017	Western	COMM	Worker	Worker was climbing a ladder and missed a rung and fell backwards. Worker was knocked unconscious.
29	02-03-2017	Central East	COMM	Worker	Beam fell and struck worker in the leg from the knee down and worker sustained a fracture to leg
30	03-03-2017	Central east	COMM	Worker	Worker fell from ladder sustained fracture to the right ankle.

MOL REPORT TO PLMHSC –JUNE 2017 MEETING

31	04-03-2017	Eastern	HYDR	Worker	Worker was doing maintenance on excavator, caught foot in step and broke lower part of leg and bones in ankle.
32	06-03-2017	Central East	RESM	Worker	Worker stepped over a bundle of rebar and slipped due to ground being wet. Worker used his arm to brace his fall resulting in a fracture wrist.
33	06-03-2017	Western	RESS	Worker	Worker fell off front porch slab onto ground and sustained shattered wrist and two fractured vertebrae.
34	07-03-2017	Eastern	COMM	Worker	Worker slipped while a backhoe was moving and the bucket pinched the worker between the bucket and ground. Worker sustained broken foot and sprained ankle. "
35	07-03-2017	Western	RESM	Worker	Worker was doing drywall work fell down form a scaffold fracturing his elbow.
36	08-03-2017	Western	RESS	Worker	Workers were framing on the second floor of a residential house and part of a pine tree broke landing on workers. A worker suffered broken rib, dislocated hip and crushed ankle.
37	08-03-2017	Western	ETTL	Worker	Worker slipped in mud twisted ankle and sustained fracture fibula of leg.
38	09-03-2017	Central West	RESM	Worker	Worker building a concrete form stepped down to another level and accidentally rolled his ankle resulting in a fractured ankle.
39	10-03-2017	Central West	SUBW	Worker	Worker fell while entering a bull dozer resulting in a fractured leg.
40	2017-03-11	Eastern	INDU	Worker	Worker fell approx. 53 inches hitting head on the side of a trough filled with water. Worker lost consciousness
41	2017-03-11	Western	INDU	Worker	Worker was attempting to rig a metal coil; it flipped over onto the worker and his legs became trapped. worker suffered multiple fractures to leg
42	16-03-2017	Central East	SEWW	Worker	Worker slipped and fell while servicing a crane. Sustained fracture to the knee.
43	17-03-2017	Central East	COMM	Worker	Worker fell 12 to 13 feet from scaffolding and lost consciousness and was bleeding from head.
44	17-03-2017	Central East	RESM	Worker	Worker was working on an elevator form and lost their balance falling 4 ft into an elevator sump pit and sustained a fracture to arm.
45	18-03-2017	Eastern	RAIL	Worker	Worker was struck in the head by a rubber hose used for pouring concrete. Worker lost consciousness
46	19-03-2017	Northern	BRID	Worker	Worker was on ladder (6.5 feet in the air) removing pipes off a truck when pipe slipped from position. Worker jumped off ladder and fractured their knee.

MOL REPORT TO PLMHSC –JUNE 2017 MEETING

47	22-03-2017	Western	INDU	Worker	Worker had the bucket of a back hoe fall onto their leg, worker sustained a broken ankle.
48	2017-03-24	Western	SEWW	Worker	Public vehicle struck worker who lost consciousness.
49	27-03-2017	Northern	EXCA	Worker	Worker directing vehicle backing up at work site, slipped on a patch of ice and fell and sustaining fracture to leg.
50	27-03-2017	Central East	RESM	Worker	Worker attempting to access Baker style scaffold platform, when the platform gave way. Worker fell approximately 5 ft. sustaining fracture to arm.
51	01-04-2017	Northern	NECC	2 Workers	Equipment operator made contact with live wires on the truck, this resulting in 2 workers being shocked and critically injured
52	03-04-2017	Western	RESS	Worker	Worker Installing truss that wind caught, worker fell and broke ankle.
53	03-04-2017	Western	RESS	Worker	Worker fell from the second floor into open stairwell landing on his side onto a concrete foundation wall. Worker broke several ribs and a punctured lung
54	04-04-2017	Western	INDU	Worker	Worker fell through a skylight a distance of approximately 8 meters.
55	06-04-2017	Western	COMM	Worker	Worker fell through drywall ceiling on to the display case and on to floor and fractured shoulder.
56	07-04-2017	Central East	INST	Worker	Wind caused the tent to fly and one worker was raised along with the tent. Worker hit the side of a building and fell approximately 30 foot. Suffered head injuries and broken arm
57	10-04-2017	Central East	RESM	Worker	A piece of 2 x 4 fell and injured a worker's forearm. Worker sustained a fracture to forearm
58	11-04-2017	Central East	HYDR	Worker	Worker was striking and holding piece of plywood over a pipe. Plywood broke and struck workers' right wrist causing a hairline fracture.
59	17-04-2017	Western	INDU	Worker	Worker was standing on the forks of forklift fell and injured head
60	17-04-2017	Central East	RESS	Worker	Horizontal steel beam fell on workers shoulder. Worker sustained a gash on chest, broken collar bone, broken arm.
61	17-04-2017	Central East	SEWW	Worker	Worker slipped and fell into 9-10ft trench and shattered ankle.
62	17-04-2017	Central West	RESS	Worker	Worker was climbing up a ladder (over 10 ft high) and the base of the ladder slipped back and the worker fell onto a grassy area and fractured arm

MOL REPORT TO PLMHSC –JUNE 2017 MEETING

63	19-04-2017	Eastern	COMM	Worker	Worker injured when jack support fell over and struck worker cutting to the bone resulting in fracture
64	20-04-2017	Eastern	RESS	Workers	Worker fell off an eight foot ladder and suffered compound fracture
65	26-04-2017	Central West	INDU	Workers	A piece of equipment fell injuring two workers, one worker was trapped and leg was crushed. The second worker injured was in shock with back injury.
66	26-04-2017	Central West	RESS	2 Workers	Two workers fell from scaffolding onto mud and rock; both workers sustained head/neck/back trauma
67	26-04-2017	Central West	RESM	Worker	Worker was putting up partition wall when the wall fell on worker. The worker sustained a compound fracture of the leg;
68	28-04-2017-	Central West	HYDR	Worker	Worker hit in back of head with air ratchet and sustained loss of consciousness; laceration to left side of head.
69	03-05-2017	Western	ROAD	Worker	Worker fractured ankle when he slipped on a muddy bank and fell approx. two feet to the ground below.
70	04-05-2017	Eastern	RESS	Worker	Worker fell off ladder against side of house, approx. ten-twelve feet and fracture forearm and wrist.
71	08-05-2017	Eeastern	INST	Worker	Worker was struck by backhoe sustaining internal injuries and broken pelvis.
72	08-05-2017	Western	COM M	Worker	Worker fell out of telehandler and sustained fractured ribs and hip.
73	08-05-2017	Western	RESS	Worker	Framer fell off the roof while installing sheathing resulting in fracture to leg.
74	10-05-2017	Central East	RESM	Worker	Worker slipped on a small ramp and fractured wrist.
75	15-05-2017	Central East	SUBW	Worker	Worker fell five feet off scaffold platform and fractured their arm.
76	16-05-2017	Western	RESS	Worker	Worker fell 8 to 10 ft when the ladder slipped down and the worker fell onto a concrete rear patio. The worker broke left rib had and difficulty breathing.
77	17-05-2017	Central west	COM M	Worker	Construction fence fell onto worker who sustained a fractured arm.
78	18-05-2017	Western	PAVE	Worker	A truck driver broke their arm when disconnecting the trailer from the truck; the 'tongue' of the trailer pinned the worker's arm between it and the tow point.
79	19-05-2017	Western	PAVE	Worker	A worker walking alongside an asphalt paver stepped on a patch of clay which broke, causing the worker to roll and fracture their ankle.
80	23-05-2017	Central East	NECC	Worker	Worker was moving material with a jack when the material fell off the jack and landed on their foot and fracturing their foot.
81	24-05-2017	Eastern	COMM	2 workers	Two workers on elevating work platform were injured when the boom failed and fell to the ground. Workers may have lost consciousness. MOL confirmed critical injuries sustained by both workers.

MOL REPORT TO PLMHSC –JUNE 2017 MEETING

82	26-05-2017	Western	RESS	Worker	Worker fell from a ladder and grabbed the ladder on the way down cutting their hand while falling to the ground at a height of 6 or 7 ft high. The worker fractured their wrist.
83	28-05-2017	Central West	CONY	Worker	Worker fell from a ladder to concrete walkway and sustained head injuries
84	29-05-2017	Central West	SEWW	Worker	Worker was working as a signalman and was struck by a vehicle sustaining critical injuries.
85	30-05-2017	Central West	NECC	Worker	Worker was installing corner bead off of a two-step bench when bench collapsed and fractured workers wrist and elbow.

Legend Sector Description

NECC - Not elsewhere captured construction

CONY – Construction premises

SEWW - Sewer/Watermain Construction

RESS - Single Family Housing

COMM - Commercial Building Construction

RESM - Apartment & Other Multiple Housing

POWP - Hydroelectric Power Plants & Rel

PAVE - Asphalt Paving

INST - Institutional Building Construction

IND - Industrial Building Construction

HYDR - Hydro

SUBW - Subway

BRID - Bridge Construction

RAIL - Railway

EXCA - Excavation

ROAD - Highway & Road Construction